



Temperatura max. 160°C

Mat. PA12

a	b	L	c
2	6,5	205	6
	8,5		8
	10,5		10
	12,5		12
	14,5		14
	16,5		16
	18,5		18
	20,5		20

Esempio d'ordine: b = 10,5 → LDPA-10,5

GUIDA
ALL'APPLICAZIONE

