



Mat. 1.7139  
ca. 700 HV



d1	d2	d3	H	k
15	11	6,6	8,4	10
22	14,5	9	11	14
36	17,5	11	13,5	20
46	20	14	15,5	25
56	26	18	21	32

Esempio d'ordine: d1 = 36 → PKN101-36

Mat. 1.7139  
ca. 700 HV




d1	d2	k
12	4,5	3
		9
		10
14	5,5	3
		5
		9
		10
		14
16	8,5	19
		3
		5
		9
20	8,5	10
		19
		3
		9
25	8,5	20
		10

d1	d2	k
25	8,5	20
26		3
		9
30	11	10
		20
		30
		4
32	11	10
		20
		30
42	11	4
		10
		20
54	13,5	20
		40
80	17,5	20
		40

Esempio d'ordine: d1 = 20 k = 10 → PKN61-20x10

Temperatura max. 250° C

Mat. 1.0715



d1	d2	H	L	P1 (N)	P2 (N)
M3	1,5	0,4	7	3	4,5
M4	2,5	0,8	9	8,5	14
M5	3	0,9	12	8	
M6	3,5	1	14	11	18
M8	4,5	1,5	16	18	31
M10	6	2	19	24	45
M12	8	2,5	22	26	49
M16	10	3,5	24	41	86
M20	12	4,5	30	56	111

Esempio d'ordine: d1 = M16 → SRM-M16